

FIRMWARE UPDATED CONTENT AND FUNCTION DESCRIPTION

Evoke 1200 V0.02.02

Version	Upgraded	Firmware Version	Date
V1.0	<ol style="list-style-type: none">1. Add Lumenradio prompt.2. Fix the problem of the Lumenradio unable to update the firmware.	EVOKE_1200_Fw_V0.01.06	2021-06-02
V2.0	<ol style="list-style-type: none">1. Add App control function.2. Add DAYLIGHT 16bit mode in DMX.	EVOKE_1200_Fw_V0.01.21	2021-10-22
V3.0	Fix the display problem with a fuzzy screen in low temperature.	EVOKE_1200_Fw_V0.02.01	2022-02-21
V4.0	Optimize the underlying driver of the display.	EVOKE_1200_Fw_V0.02.02	2022-03-08

● EVOKE_1200_Fw_V0.01.06

Updated Content Description:

1. When the Lumenradio is set to transmitter mode, the screen will show "ATTENTION: WHEN USING TRANSMITTER MODE, THE CONTROLLING RANGE OF NANLINK BLUETOOTH AND 2.4G WILL BE SHORTEN".
2. Fixed the problem of the Lumenradio unable to update the firmware.

Notes:

1. The firmware of the fixture needs to be updated to version V0.01.06 before updating the firmware of the Lumenradio.
2. The firmware of the Lumenradio should be updated to 1.0.5.0 or above. Otherwise, when the Lumenradio is in receiver mode, the Lumenradio will sometimes automatically switch to transmitter mode after the fixture is re-powered.

● EVOKE_1200_Fw_V0.01.21

Updated Content Description:

1. Add App control function.
2. Add DAYLIGHT 16bit mode in DMX.

Notes:

1. Please refer to DMX reference guide for specific DMX functions.

● EVOKE_1200_Fw_V0.02.01

Updated Content Description:

1. Fix the display problem with a fuzzy screen in low temperature.

● EVOKE_1200_Fw_V0.02.02

Updated Content Description:

1. Optimize the underlying driver of the display.